



## ExpressSAS Host Adapter 6Gb v1.57 – Linux

### 1. General Release Information

---

These product release notes define the new features, changes, known issues and release details that apply to the ExpressSAS Host adapter products v1.57 that was released on 6/2/2011. This information pertains to the following Linux operating systems: Red Hat Enterprise Linux 4, 5 (x86, x64), SUSE Linux Enterprise Server 10, 11 (x86, x64), CentOS 5 (x86, x64), Fedora 12 (x86, x64) and openSUSE Linux 11.2 (x86, x64)

### 2. Changes

---

- **Version 1.57 (Released 6/2/11)**
  - **Note:** It is recommended that firmware dated 5/19/11 be utilized with this driver release.
  - **New Features, Enhancements and Changes**
    - Corrected several issues with SAS controller resets that could result in memory corruption.
    - A PHY is now permanently disabled when it has been determined that the link is unstable.
    - Corrected an issue with Mode Select processing for SATA devices where a properly formatted command may have been rejected.
    - Added a virtual SES device to control identify and fault indicators of direct attached devices. By default, the virtual SES device is disabled. Use the `atsasnr LED Control` setting to enable this device. Note that the virtual SES device will not be visible in I2C mode if no I2C controllers are found during driver initialization.
    - Modified response if an I-T nexus loss occurs for an expander during discovery. Discovery is now aborted and retried two seconds later.
    - Corrected two issues that may stall task management processing and device recovery.
    - Corrected two issues with SATA NCQ processing under heavy load that could result in temporarily slow or permanently stalled I/O.
  
- **Version 1.56 (Released 11/30/10)**
  - **Note:** It is recommended that firmware dated 11/19/10 be utilized with this driver release.
  - The following applies to changes made from release v1.50 to 1.56
  - **New Features, Enhancements and Changes**
    - Added support for H60R HBA.
    - Modified data frame offset error checking to improve Transport Layer retries.
    - Improved ease-of-use install with 2.6.30 kernel.
    - Enhanced SATA drive ID display.
    - Implemented reset method to recover from Identity frame timeout.
    - Enhanced discovery process concerning self configuring expanders.
    - Improved device reporting to the OS.
    - Added support for `hdparm`.
    - Improved interoperability with kernel versions 2.6.14 to 2.6.17.
    - Enhanced discovery process for expanders.
    - Improved stability during booting with regards to SAS transport disabling.
    - Improved interoperability with openSUSE11 and SAS transport.
    - Modified device reporting during initial discovery process.

- **Version 1.50 (Released 7/30/10)**
  - **Note:** It is recommended that firmware dated 7/27/10 be utilized with this driver release.
  - The following applies to changes made from release v1.32 to 1.50
  - **New Features, Enhancements and Changes**
    - Improved negotiation for devices behind expander which require lower rates due to partial paths.
    - Enhanced recovery from a chip reset.
    - Enhanced Discovery Process by delaying certain SATA commands, while discovery is in progress.
    - Corrected an issue where I/O could be prematurely completed with an error prior to the link down timeout expiring.
    - Corrected an issue with SCSI pass through requests initiated by the CLI tools where the command timeout was not honored.
    - Improved check condition returns with ATA Pass Through command.
    - Link negotiation to SATA devices improvements.
    - Changes made to improve the consistency of the state of SATA devices and formatting SATA commands during discovery process.
    - Improved staging of multiple SMP commands to compensate for resource deficiencies.
    - Commands pended while discovery is in progress.
    - Enhanced configuration discovery for expanders that are actively self configuring.
    - Updated the SMP connection time and PHY transmitter settings for increased uptime.
    - Improved recovery for Initiator to Target errors with expanders.
    - Corrected an issue where task management could fail because a device error could not be recovered at the same time.
    - Corrected an issue where a SATA command that was aborted and then retried could be erroneously aborted again.
    - Enhanced SATA device retries for parity errors.
  
- **Version 1.32 (Released 3/31/10)**
  - **Note:** It is recommended that firmware dated 3/26/10 be utilized with this driver release.
  - The following applies to changes made from release v1.30 to 1.32
  - **New Features, Enhancements and Changes**
    - Enhanced interoperability for SuperMicro chassis with expanders.
    - When an IDENTIFY frame timeout occurs on an expander and/or a controller PHY, a link reset is issued to each PHY to attempt link recovery.
    - Improved controller initialization to allow backup firmware built into the driver to load when the firmware in flash is corrupt.
    - The SMP API has been updated to allow access to the SGPIO interfaces on the controller. Firmware version 1.09 is required for SGPIO operation.
    - Task management timeout enhancements.
    - Improved device discovery during initial driver startup.
    - Additional events have been added for SMP command errors.
    - CSMI interface improvements for reporting an unknown SAS port for a PHY whose link is down.
    - Improved performance when the controller has limited resources to transmit frames within an open connection.
    - Descriptor based sense data support added.
    - Command failures due to an invalid link rate are detected with rediscovery and corrected to account for the new link rate.
    - When a valid SAS port does not exist and a hard reset sequence is detected, a PHY restart is implemented.
    - Added PHY restart when a hard reset sequence is detected, when a valid SAS port does not exist.

- For SATA drives, after a Stop Unit command has spun down the media, access commands are completed with a SCSI check condition for the message “Not Ready, Initializing Command required.”
  - Improved recovery for flash data due to a controller fault.
  - Enhanced discovery of topology changes behind an expander.
  - More efficient stack usage for event logging code.
- **Version 1.30 (Released 10/29/2009)**
    - **Note:** It is recommended that firmware dated 10/22/09 be utilized with this driver release.
    - The following applies to changes made from release v1.20 to 1.30
    - **New Features, Enhancements and Changes**
      - CSMI support added.
      - Descriptive strings for sense keys to SCSI error event logging added.
      - Failed task management commands which may have been reported to the OS as successful, were corrected
      - Enhanced discovery process after an expander routing failure detection.
      - The Immediate bit in the Start Unit command enhanced for SATA device support.
      - SATA drive enhancement when transferring I/O in multiple segments.
      - Improved device wait count setting when handling power cycle devices.
      - SMP API direct attached target discovery report enhanced.
      - Bus reset processing enables devices for I/O after reset completion.
      - Discovery resource management enhanced for improved expander PHY routing accuracy.
      - Data overruns for expander discovery commands are enhanced to support inaccuracies with expanders sending an invalid response length.
      - Removed “num\_ioreq” module parameter
      - Added “io\_time\_out” module parameter (default value of 30 seconds)
- **Version 1.20 (Released 07/31/2009)**
    - **Note:** It is recommended that firmware dated 07/27/09 be utilized with this driver release.
    - The following applies to changes made from release v1.10 to 1.20
    - **New Features, Enhancements and Changes**
      - Enhanced firmware which contributed in an up to 25% increase in throughput.
      - The supported expander chain depth was increased from 8 to 10.
      - Transport layer retries are explicitly enabled on all commands for SAS 2.0 compliant devices instead of being enabled in the device’s mode pages.
      - All command retries are disabled for sequential (e.g. tape) devices.
      - SMP PHY Control command for clearing SATA affiliations improved. Uses the hard reset function instead of the clear affiliation function.
      - Expander enhancements which include discovery process reorganization for clearing SATA affiliations. All devices reported to the OS will have sequential target IDs starting with zero.
      - The heartbeat mechanism has been redesigned to improve I/O resources allocation.
      - Confirmation of I/O completion to the OS prior to reporting a device removal.
      - SCSI check status for data phase errors and other bus events that occur due to signal integrity problems are now retried
      - When a port is reset due to a task management command timeout, the aborted collateral is retried.
      - Enhanced event logging to include retried commands
      - Added support to the SMP API for discovering direct attached devices. A SAS address can be associated with all target IDs.
      - Changed the scatter/gather allocation to improve performance and conserve memory.
      - Improved optimizations and memory allocation to expander discovery process to increase number of drives that can be discovered.
      - Stability fixes in discovery processing when commands timeout or need to be retried due to bus errors.
      - Fixes to SATA NCQ error and head-of-line blocking recovery mechanisms to ensure commands are properly aborted and retried.

- Task management processing correction for when a discovery is in progress for the same port.
  - When a device rejects an OPEN address, it is infinitely retried to account for devices that stop responding to commands for extended periods of time.
  - Resolved compilation error for kernel 2.6.29 and newer.
  - Fixed resource leak when aborting commands that can eventually lead to failing commands.
  - Return codes from the abort handler repaired
  - The OPEN REJECT RETRY interval is set to 5  $\mu$ s.
- **Version 1.10 (Released 03/24/2009)**
    - **Note:** It is recommended that firmware dated 03/20/09 be utilized with this driver release.
    - The following applies to changes made from release v1.01 to 1.10
    - **New Features, Enhancements and Changes**
      - Added the Device Name field to the SAS Identify Address Frame (an optional field added in SAS 2.0).
      - Resolved an issue during initial device discovery that could result in a driver crash if the device rejects a discovery command.
      - Resolved issues with discovery processing when a discovery command timed out
      - SATA devices behind expanders are no longer reset during discovery
      - Improved SATA NCQ processing so performance is maintained as the queue depth increases
      - Improved port down cleanup to ensure all I/O is completed before destroying devices when multiple ports are instantiated
      - Resolved an issue with SCSI-to-ATA translation of the WRITE AND VERIFY commands that would allow NCQ commands to be started between the write and verify phases
      - Now support SMP API
      - Added timeout processing for commands issued through the SMP API
      - SATA NCQ is disabled in NVRAM by default
- **Version 1.01 (Released 02/18/2009)**
    - **Note:** It is recommended that firmware dated 01/28/09 be utilized with this driver release.
    - The following applies to changes made from release v1.00 to 1.01
    - **New Features, Enhancements and Changes**
      - Resolved issues that may cause the driver to crash or hang if a device rejects a discovery command on initial load.
      - Resolved any unexpected target ID changes after a cable pull and reinsertion, when a SATA device is connected behind an expander..
- **Version 1.00 (Released 12/11/2008)**
    - **Note:** It is recommended that firmware dated 2008\_12\_05 be utilized with this driver release.
    - The following applies to release v1.00
    - **New Features, Enhancements and Changes**
      - Initial release of ExpressSAS H608 and H680

### 3. Known Issues/Advisements

---

- Please refer to the DOS release notes for any known firmware issues.
- SAT exceptions: (SCSI-to-ATA Translation for SATA support). The following SCSI commands are not translated: FORMAT UNIT, REASSIGN BLOCKS, SECURITY PROTOCOL IN, and SECURITY PROTOCOL OUT.

#### 4. Affected Products

---

Product Name
ExpressSAS H680 Host Adapter
ExpressSAS H608 Host Adapter
ExpressSAS H6F0 Host Adapter
ExpressSAS H60F Host Adapter
ExpressSAS H644 Host Adapter
ExpressSAS H60R Host Adapter

#### 5. Contacting ATTO Support

---

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: [techsupport@attotech.com](mailto:techsupport@attotech.com)